ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0545	NA	Thindlu
Segment No.	**Total Length (m)**	
9/S-W0545/S055946	32.01	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	32.01	77.569174	13.074605	77.569156	13.074316	Kunte connecting road	thindlu main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains at Thindlu colony in ward no 09 (Vidyaranayapura)	2500000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	CC road and drain
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	CC road and drain	009-18-000004
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/32/2017-18	20/12/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
20/12/2017	20/12/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

eld Inspection Details

Number of Trees	Any Other Information	Name
0		krishnappa
Date of Inspection	**Remarks**	
16/02/2018		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	21/02/2018	18/03/2018	As proposed.
SE	Vasu K M	21/02/2018	18/03/2018	Completed
EE	Mohandas H.T	16/02/2018	18/03/2018	verify
AEE	~~Krishnappa~~ SHIVAKUMAR	16/02/2018	18/03/2018	verify
AE	Krishnappa	16/02/2018	18/03/2018	Mobile verification is done
AE	Krishnappa	16/02/2018	18/03/2018	Forwarded